



Differences of 3.00 vs IC
 - EEPROM & jumpers removed - No bankswitch logic
 - Divider GAL replaced by 7474